




BEAM AND PULLEY AT HAY DOOR



EXISTING LIGHT FIXTURE



(FRONT) SOUTH ELEVATION





EAST ELEVATION



(REAR) NORTH ELEVATION





HAY DOOR & BLOCKED STALL WINDOW




ENTRANCE TO UNDERGROUND GARAGE






HOTEL EMERGENCY EXIT





TYPICAL WINDOWS



EMERGENCY DOOR TO BE CLOSED