

Exhibit A. Before and After Impact Photos on my home and property at 1225 E St.

Figure 1. Current view from sunporch



Figure 2. Rendition of view from sunporch with proposed extension



**The Applicant's architect noted at the ANC6B October 12 meeting that they proposed project material will be hardy board, not brick. The intent of sharing this rendition is to demonstrate the loss of view, air, and spaciousness that I am concerned about. What material is used to build this wall is not material to the impacts on me.*

Fig 3. Sunporch with plants



Fig. 4. Current backyard, 10-19 foot from my rear deck, straight view




Fig 5. Backyard, 10-19 foot from my rear wall, looking up



Fig 6. Rendition of Proposal Backyard, 10-19 foot zone



**The Applicant's architect noted at the ANC6B October 12 meeting that they proposed project material will be hardy board, not brick. The intent of sharing this rendition is to demonstrate the loss of view, air, and spaciousness that I am concerned about. What material is used to build this wall is not material to the impacts on me.*




Figure 7. Cherry tree on property line, soil compacted from the proposal in its critical root zone will severely damage this tree

Figure 8. Looking east from 1225 E St, 23.5 feet from my rear wall



Figure 9. Looking west from 1225 E St, 23.5 feet from my rear wall

