
CLOSE-UP OF DAMAGE TO ROOTS OF
34" TULIP POPLAR TREE

2221 30TH ST. N.W.





HOUSE DEMOLISHED WITHOUT VALID PERMIT

29" TULIP TREE AT RISK



2221 30TH ST NW



29" TUIP POPLAR TREE NOW AT RISK







THE 31" TULIP POPLAR WAS LOCATED BETWEEN THE GREEN WALL AND THE BRICK WALL OF THE GARAGE WITH A CINDERBLOCK RETAINING WALL UNDERNEATH.

LOCATION OF 31" TULIP POPLAR TREE WHICH WAS CUT ↓ DOWN 7/19/2001





DEMOLITION OF GARAGE ←

LOCATION OF THE 31" TULIP POPLAR THAT WAS CUT DOWN 7/19/2001




DEMOLITION OF EXISTING STRUCTURE CAUSED GROUND TO SHIFT →

8/21/2001

"In my opinion, the demolition of structures around the retaining wall and disturbance of soil in the tree's critical root zone resulted in the structural instability of the tree, which was noted in the Lee's Tree Service memo.

Joseph Christopher
ISA Certified Arborist, Licensed Tree Expert

2221 30TH ST NW




29" TUIP POPLAR TREE NOW AT RISK





2221 30TH ST. N.W.





HOUSE DEMOLISHED WITHOUT VALID PERMIT

29" TULIP TREE AT RISK







CREW WORKING AT 2231 30TH ST.
SATURDAY, SEPT. 22ND AT 6:45 P.M.
IN VIOLATION OF SUSPENDED
BUILDING PERMIT




DAMAGE TO BARK OF FATALLY DAMAGED
34" TULIP POPLAR TREE 8/2/01
8/2



EXTENSIVE EXCAVATION & DAMAGE TO ROOTS OF 34" TULIP POPLAR TREE





CONSTRUCTION EXCAVATION MADE WITHIN THE CRITICAL ZONE OF THE ROOTS OF THE 34" TULIP POPLAR

34" TULIP POPLAR VIEWED FROM THE EAST


ACTIVITY RESUMED 8/28/01



Building Permit

[redacted] 35446
2221 30th St
LOT 6 SQUARE 2198

Call Vince Ford 442-4558 or 9 Estelle Brown, Asst



THE 31" TULIP POPLAR WAS LOCATED BETWEEN THE GREEN WALL AND THE BRICK WALL OF THE GARAGE WITH A CINDERBLOCK RETAINING WALL UNDERNEATH.

LOCATION OF 31" TULIP POPLAR TREE WHICH WAS CUT ↓ DOWN 7/19/2001




HEAVY EQUIPMENT TRACKS NEXT TO
34" TULIP POPLAR TREE (no protection)
8/7