P2

THURNTON, JOHN
5300 QUEBEC ST NW
WASHINGTON, DC 20008-
(202) 364-6663
(202) 879-6161

06/05/2002
1 1

1991 PONT GRAND PRIX
EWM813 BLACK
05/189/3.1 AUTO
4

SUBTOTAL 0.00

CO 003 OM TEST COOLING SYSTEM FOR OVERHEATING 35.75

SUBTOTAL 35.75

Dona Stairs

Repair Work Orders Obtained
On Site By M. Hooks

Case No. 16947
Exhibit No. 37

Board of Zoning Adjustment
District of Columbia
CASE NO.16947
EXHIBIT NO.37

[illegible] 1
04/05/2002

NOIRA, JOHN
4301 CONN AVE #433
WASHINGTON, DC 20008
(202) 537-1050 W
( ) --

1986 JEEP XJ6
JWN TAN
SAJHV1846GC446[illegible]
4.2 AUTO
4

1.00 FILTER	OIL FILTER	9.95	PM 001 00	PACKAGE-OIL,FILTER & LUBE 35.95		16.00
5.00 MOTOR OIL	OIL	10.00		TOP OFF FLUIDS, VISUAL SAFETY		
	OIL DISP. FEE	2.00		INSPECTION.		
		---	PM 005 00	SUMMER CHECK UP SPECIAL $39.95		39.95
	SUBTOTAL	19.95	CC 001 00	CHECK SPEEDO & DOOMETER		0.00
				OIL LEAK		

					SUBTOTAL	55.95

[illegible]
[illegible]
[illegible]

[illegible]
[illegible]
[illegible]
[illegible]

[illegible]
[illegible]

A

00054643- 2
05/05/2002
1 1

VAZQUEZ, EDWARD
3001 DAVENPORT ST NW
WASHINGTON, DC 20008-
(202) 966-9000 H
(202)

1993 JEEP GRAND CHEROKEE
BK6916 BLACK

--------- DC 001 02 CHECK FAILED D.C. INSPECTION 0.00
SUBTOTAL 0.00 ---------
SUBTOTAL 0.00

6

06/05/2002

[illegible]

[illegible]
2013 PARK RD #3 NW
WASHINGTON, DC [illegible]
(202) 462-5047
(202)

1967 FORD THUNDERBIRD SW
94A65X9 RED

3.9L AUTO

4

1.00 TRANSM.KIT	46.40	CC 001 00	CHECK TRANS SERVICE $175.00		0.00
5.00 TRANSM.FLUID	17.50	1R 001 00	CHANGE TRANSMISSION KIT & FLUIDS		84.00
SUBTOTAL	63.90			SUBTOTAL	84.00

[illegible]

0005691-- 1
06/05/20002
1 1

GOLLSTEIN, MICHAEL
3507 LOWELL ST NW
WASHINGTON DC 20016
(202) 337-3838 H
(202) 776-2569 W

1993 FORD TAURUS
233635 GREEN
1FALP52U2PA244569
V6/232/3.8 AUTO
4

1.00 FILTER	OIL FILTER	9.95	PM 001 00	PACKAGE-OIL,FILTER & LUBE 35.95			16.00
5.00 MOTOR OIL	OIL	10.00		TOP OFF FLUIDS, VISUAL SAFETY			
	OIL DISP. FEE	2.00		INSPECTION.			
		--------	CC 001 00	CHECK OIL LIGHT ON			0.00
	SUBTOTAL	19.95	PM 006 00	SUMMER CHECK UP SPECIAL 139.95			39.95
						SUBTOTAL	55.95

[illegible]

0005465?-- 3
05/05/2002
1 1

SEIFERT, MARK
1836 LAMONT ST NW
WASHINGTON, DC 20010-
(202) 483-3066
(PAG) 418-7300

1991 BMW 318I
77340 BROWN

1.8L DOHC
53747 2 MATCH

1.00 TB	TIMING BELT	67.42	CC 001 00	CHECK REPLACING TIMING BELT	0.00
2.00 CAM SEAL		14.50	SM 001 12	TIMING BELT TENSIONER	36.75
1.00 CRANK SEAL		14.35			
1.00 TB	T.BELT TENSIONER	63.15		SUBTOTAL	36.75
	SUBTOTAL	159.42			

36.75
159.42
0.00

[illegible]
1 [illegible]
1 [illegible]
2 [illegible]

[illegible]
[illegible]

E

0005×6589- 2
06/05/20002
1 1

BAUER, BRIAN
3225 IDAHO AV NW
WASHINGTON, DC 20016-
(2002) 491-4233 CELL
(202)

1969 HOND ACCORD
T47ETN WHITE
JHMCA5539KC027588B6
2.0 5 SPEED
4

--------- CC 001 00 CHECK STRAIGHTSN LEFT HEADLIGHT ASSEMBLY 0.00

SUBTOTAL 0.00

SUBTOTAL 0.00

BB

0.00
0.00
0.00

0.00
0.00
0.00
0.00

0.00
0.00

0034490-- 1
06/05/2002
1 1

WALLING, OLIVIA
1855 CALVERT ST NW#101
WASHINGTON, DC 20009-
(202) 265-1401
(202)

1995 HARLEY 9000
PU1570 SILVER

1.00 FILTER	OIL FILTER	9.95	PM 001 00	PACKAGE-OIL,FILTER & LUBE 35.95	16.00
5.00 MOTOR OIL	OIL	10.00		TOP OFF FLUIDS, VISUAL SAFETY	
	OIL DISP. FEE	2.00		INSPECTION.	
	SUBTOTAL	19.95		SUBTOTAL	16.00

SS

16.00
19.95
0.00

2.00
1.97
0.00
0.00

0.00
0.00

6