



P1 - Top of berm, small stems would be removed.



P2 - Length of berm from parking lot.



P3 - Corner of berm impacted by building.



P4 - Weeping cherry and oak (in distance) impacted by wall.

Case No. 17055
Exhibit No. 134

Board of Zoning Adjustment
District of Columbia
CASE NO. 17055
EXHIBIT NO. 134