EROSION

AND MORE!



Board of Zoning Adjustment
District of Columbia
CASE NO.17192
EXHIBIT NO.41A3

EROSION

- **EROSION** HAS CAUSED THE STAIRWELL TO PULL AWAY FROM THE ENTRY TO THE UNIT



- NOW IS THIS SAFE?

EROSION

- AND AGAIN!



EROSION

- AND AGAIN!
- SEE THE CLAY?



EROSION

- AND AGAIN!



EROSION

AND AGAIN!




EROSION

- AND AGAIN!




EROSION

- WILL THE STAIRWELL EVENTUALLY CRUMBLE COMPLETELY?




STROM DRAIN


- DID THE DRAINS EVER WORK? WAS IT INSTALLED CORRECTLY?
- WHERE WERE THE DEVELOPERS AND MANAGEMENT COMPANIES?




INORPERABLE STROM DRAIN



CLOSE-UP SHOT OF STROM DRAIN



I NOPERABLE STROM DRAIN #2





CRACKED STRUCTURE



PERPETUALLY WET GROUND



PERPETUAL SWAMP



PERPETUAL SWAMP



IS IT MOLD OR WHAT?



IS THIS MORE MOLD?



WHY ARE WE EXPECTED TO LIVE WITH THIS



Close-up View



ADJACENT YARD



PERPETUAL SWAMP



PERPETUAL SWAMP



ARE WE HOMEOWNERS OR WHAT?

WHY SHOULD WE PAY MORTGAGES TO LIVE LIKE THIS?

EXHIBIT 39
Report of Watershed Protection Division
Department of Health