Lot 105 Square 93

Washington, D.C.

Scale: 1"= 20'

Surveyor's Certificate

We hereby certify that we have carefully examined the property shown hereon in accordance with record description; that all of the existing buildings have been located by a transit-tape survey; that lot corners have not been set by this survey unless otherwise shown:

Date: September 10, 1984

Liber 12
Folio 118


Recertified September 3, 1985

Recertified Jan. 12, 1987

Frey, Sheehan, Stoker & Assoc.,Inc.
Land Planning Consultants
Phone 588-3110

By: James F. Sheehan
James F. Sheehan
Professional Land Surveyor
Md. No. 3984

STATE OF MARYLAND
JAMES F. SHEEHAN
PP
No. 3994
REGISTERED
LAND SURVEYOR



HILLYER PLACE, N.W.

BZA
Case No. 17247
Exhibit No. 4

The lot hereon does not lie within flood hazard Zone A or Zone B as determined by Department of Housing and Urban Development, Federal Insurance Administration.

Board of Zoning Adjustment
District of Columbia
CASE NO. 17247
EXHIBIT NO. 4

82-1540