


Fastener & Hanger Note:

New methods of pressure treating wood require heavier zinc coatings on plate and gauge steel connectors and fasteners. All plate and gauge steel connectors and fasteners shall be silicon zinc or post batch hot-dip galvanized wherever they contact pressure treated wood.



ADDITIONAL FRAMING DETAILS

Note: all footings shall be cast-in-place concrete

WARNING
This drawing is not to be used for construction of the minimum requirements. It is not a plan and specification. MARYLAND DOES NOT A MANNER OR TO ANY E DRAINING. Persons to should not rely on it. MARYLAND DISCLAIMS DAMAGES OR INJURY ARISING OUT OF IT.