


NOTE: BOUNDARY INFORMATION SHOWN HEREON WAS OBTAINED FROM OFFICIAL RECORDS, AND MAY NOT NECESSARILY AGREE WITH ACTUAL MEASURED DIMENSIONS. PROPERTY CORNER MARKERS NOT INSTALLED BY THIS SURVEY UNLESS OTHERWISE INDICATED HEREON.

NOTE:

PROPERTY SHOWN AMONG THE RECORDS OF THE D.C. SURVEYORS OFFICE AS FOLLOWS:
SUBDIVISION BOOK 41 - PAGE 70.
SURVEY BOOK 181 - PAGE 320.
ASSESSMENT & TAXATION PLAT 756.



NOTES:

1. TOTAL AREA: 1633 sq. ft. OR 0.0375 AC.
2. NO TITLE REPORT FURNISHED. EASEMENTS, IF ANY, NOT SHOWN.

ENGINEER'S - SURVEYOR'S CERTIFICATION:

I HEREBY CERTIFY THAT THE POSITIONS OF ALL OF THE EXISTING IMPROVEMENTS ON THE PROPERTY SHOWN BY THIS PLAT HAVE BEEN CAREFULLY ESTABLISHED BY A TRADUIT-TAPE SURVEY, AND THAT UNLESS OTHERWISE SHOWN HEREON THERE ARE NO ENCROACHMENTS.

JULY 19, 1985

David S. Weber

DATE.

DAVID SAMUEL WEBER,
DISTRICT OF COLUMBIA
PROFESSIONAL ENGINEER No. 7961-CIVIL.



LOCATION OF IMPROVEMENTS.

LOTS 811 AND 812,
(ORIGINALLY RECORDED AS LOT 42)
SQUARE 756,
DISTRICT OF COLUMBIA.
SCALE: 1 IN. = 16 FT. JULY, 1985.

A. Morton Thomas & Assoc., Inc.
REGISTERED PROFESSIONAL ENGINEERS AND LAND SURVEYORS
10750 TWOHOCK PARKWAY, SUITE 200
ROCKVILLE, MARYLAND 20850
TELEPHONE: (301) 681-2545
A.M.T. FILE NO: H-85-2710

Board of Zoning Adjustment
District of Columbia
CASE NO. 19014
EXHIBIT NO. 5