



U.S. Department of Homeland Security
UNITED STATES SECRET SERVICE

Washington, D.C. 20223

To: Bishop Barry C. Knestout

Holy See Embassy Address: 3339 Massachusetts Avenue, NW

A Security & Fire Emergency Review of the Holy See Embassy

Security Review Points.

1. Fence around complex: suggested height 6 feet
2. Front Door lock: Change to minimal of 1 inch thick deadbolt
3. Mail Handler: Check all mail before being delivered to Embassy, establish policies for suspicious /hazardous items
4. In the Rear of the location change all locks on all glass single pane doors to keyed deadbolt locks: keyed on both sides of lock
5. Camera system: Capabilities of keeping records up to and at least 30 days / Camera Locations towards Front Door, Rear Doors, Side Doors
6. Entry Door system to allow access for personal (allows doors to be lock and keep intruders out)(Key Fob, Card Reader, Numerical Key Pad)

Fire Hazard Concerns.

1. Cement Block & Metal Bars covering windows & doors on 1st & 2nd floors: Be removed or replaced with egress access
2. Add additional Fire Extinguishers to the rooms that are sealed by the cement or metal window coverings
3. Have Building Fire Pull Alarms check by DC Fire Department to see if in working order

Christopher Smith
Sergeant
Foreign Missions Branch

BOARD OF ZONING ADJUSTMENT
District of Columbia

CASE NO. 19013

EXHIBIT NO. 11

Board of Zoning Adjustment
District of Columbia
CASE NO.19013
EXHIBIT NO.11