


Davis-Nassef Residence
4458 Greenwich Parkway NW

Overview



Framing View





FIGURE 10: JOIST-TO-BEAM CONNECTION






FIGURE 18: NOTCHED 6x6 POST-TO-BEAM CONNECTION



Board of Zoning Adjustment
District of Columbia
CASE NO.21173
EXHIBIT NO.23