


CASE #: DC-19-873





LEGEND:

- FENCE

BASEMENT ENTRANCE

BAY WINDOW BR - BRICK

- BLDG. RESTRICTION LINE BRI

BSMT C/S - BASEMENT - CONCRETE STOOP CONC - CONCRETE

D/W UP FR MAC - DRIVEWAY - UTILITY POLE FRAME - MACADAM

- WINDOW WELL - OVERHANG - UTILITY BOX

COLOR KEY:

- RECORD INFORMATION - IMPROVEMENTS (RED) (BLUE) - ESMTS & RESTRICTION LINES

LOCATION DRAWING OF:

#2016 1ST STREET NW

LOT 11 SQUARE 3116

WASHINGTON, D.C.

LIBER: Co. 15 FOLIO: 13


SCALE: 1"=20' DATE: 05-07-2025

DRAWN BY: AP FILE #: 253619-512

SURVEYOR'S CERTIFICATE HEREBY STATE THAT I WAS IN RESPONSIBLE CHARGE OVER THE PREPARATION OF THIS DRAWING AND THE SURVEY WORK REFLECTED HEREIN. THIS SURVEY IS NOT TO BE USED OR RELIED UPON FOR THE ESTABLISHMENT OF FENCES, BUILDING, OR OTHER IMPROVEMENTS, THIS PLAT DOES NOT PROVIDE FOR THE ACCURATE IDENTIFICATION OF PROPERTY BOUNDARY LINES, BUT SUCH IDENTIFICATION MAY NOT BE REQUIRED FOR THE TRANSFER OF TITLE OR SECURING FINANCING OR REFINANCING. THIS PLAT IS OF BENEFIT TO A CONSUMER ONLY INSOFAR AS IT IS REQUIRED BY A LENDER OR A TITLE INSURANCE COMPANY OR ITS AGENTS IN CONNECTION WITH THE

CONTEMPLATED TRANSFER, FINANCING OR REFINANCING. THE LEVEL OF ACCURACY FOR THIS DRAWING IS 1's. NO TITLE REPORT WAS FURNISHED TO NOR DONE BY THIS COMPANY. SAID PROPERTY SUBJECT TO ALL NOTES, RESTRICTIONS AND EASEMENTS OF RECORD. BUILDING RESTRICTION LINES AND EASEMENTS MAY NOT BE SHOWN ON THIS SURVEY. IMPROVEMENTS WHICH IN THE SURVEYOR'S OPINION APPEAR TO BE IN A STATE OF DISREPAIR OR MAY BY CONSIDERED "TEMPORARY" MAY NOT BE SHOWN. IF IT APPEARS ENCROACHMENTS MAY EXIST, A BOUNDARY SURVEY IS RECOMMENDED

15' ALLEY




1ST STREET NW

A Land Surveying Company



DULEY and Associates, Inc.



14604 Elm Street, Upper Mariboro, MD 20772 Phone: 301-888-111 Board of Zoning: Adjustment4 Email: orders@duley.biz

CASE NO.21335

