#### BEFORE THE DISTRICT OF COLUMBIA BOARD OF ZONING ADJUSTMENT

APPLICATION OF 2805 M STREET, LLC

ANC2E06

#### STATEMENT OF THE APPLICANT

#### I. NATURE OF RELIEF SOUGHT

This statement is submitted on behalf of the Applicant, 2805 M STREET, LLC (the "Applicant"), the owner of the property located at 2805 M Street NW (Square 1212, Lot 0201) (the "Property"), in support of its application for special exception relief from the requirements for a fifteen foot rear yard under DCMR Subtitle G § 405.2 in connection with the construction of stairs leading to the second floor of an existing building at the Property.

#### II. JURISDICTION OF THE BOARD

The Board of Zoning Adjustment (the "Board") has jurisdiction to grant the special exception and variance relief requested herein pursuant to Subtitle X § 901.2; 1000.1 of the Zoning Regulations.

#### III. BACKGROUND

#### A. The Property and the Surrounding Neighborhood

The Property is in the MU-4 Zone District with a lot area of 5,130 sq. ft. A copy of the zoning map is attached at <u>Tab A</u>. The Property is a rectilinear lot located at the northwest corner of the intersection of 28<sup>th</sup> Street, NW and M Street, NW. A copy of the Baist Map is attached at <u>Tab B</u>. As shown on the plans attached at <u>Tab C</u>, the Property is currently improved with a three story structure (the "Building"). The Applicant proposes to renovate the Building, which renovation will include the construction of an exterior rear stair leading to the second floor (the "Repairs") as described in more detail below and as shown in the drawings on A010 (showing the

existing conditions) and A201 (showing the Repairs). The Repairs will require special exception relief. However, as shown in the Existing First Floor Plan on Drawing No. A0006 in <u>Tab C</u>, the Property is already non-conforming under the rear yard requirement set forth in Subtitle G § 405.2 as the rear yard has a setback of four (4) foot three (3) inches at the point closest to the property line rather than the fifteen (15) feet required under the Zoning Regulations.<sup>1</sup>

The Property is located at the eastern edge of Georgetown along a commercial stretch of M Street, NW, with the façade of the Building on M Street, NW (facing south). The adjacent property along M Street, NW, 2807 M Street, NW, was most recently home to Bibibop: Asian Grill. Other restaurant and retail uses are located further along M Street, NW, including the Four Seasons Hotel, located directly across the street. The rear of the Property is adjacent to 1210 28<sup>th</sup> Street, NW, a row house in the MU-4 Zone. Properties along N Street, NW are home to restaurants, residences and offices. Restaurants and the Qatar Defense Attaché are located across N Street, NW from the Property. The Property is individually identified as historic (recognized as the Sims House, 2803 M Street) and is part of the Georgetown Historic District.

#### **B.** Traffic Conditions and Mass Transit

The Property has good public transportation options. There are several bus stops within two to three blocks of the Property, serving bus lines 30N, 30S, 31, 33, 38B, D5. There are three Capital Bikeshare stations within approximately .4 miles of the Property, including one in the median of M Street, NW adjacent to the Property. In general, the area is pedestrian-friendly, as Walkscore.com rates the Property as a "Walker's Paradise."

#### C. The Repairs

\_

<sup>&</sup>lt;sup>1</sup> As noted throughout the application the property abuts what is referenced as an alley, but it is not confirmed as a public alley as defined in Subtitle B § 1002. of the Zoning Regulations as we cannot confirm if it is recorded at the Office of the Surveyor of the District of Columbia. Out of an abundance of caution we are taking the measurement from the property line and not the alley pursuant Subtitle G § 405.5(b).

The Applicant proposes to construct a staircase at the rear of the Property for exterior access to the second floor of the Building. The Repairs are part of a larger series of renovations to improve and restore the Building following a car crash that badly damaged the 28<sup>th</sup> Street elevation, adjacent to the proposed site of the Repairs, in January, 2019. Following the crash the Applicant prepared plans for a restoration of the exterior and a renovation of the interior that have since passed the scrutiny of the Historic Preservation Review Board and the Old Georgetown Board. A copy of the architectural plans are attached at <u>Tab C</u>. It was only upon filing for permits that the Applicant realized that a permanent replacement for a stair that already exists at the Property requires zoning relief.

The Repairs will meet all of the development standards in the MU-4 Zone with the exception that the Building will continue to not meet the MU-4 rear yard requirement as the construction of the Code-compliant Repairs will involve the reduction of the rear yard to one (1) foot along sixteen (16) feet eight and one half (8.5) inches at the point closest to the property line, as more fully shown in Drawing A104 of <u>Tab C</u>.

## IV. NATURE OF SPECIAL EXCEPTION RELIEF SOUGHT AND STANDARD OF REVIEW

The Applicant requests special exception relief from the rear yard requirement as a staircase cannot be built at the rear of the Property in the MU-4 Zone without meeting the criteria for special exception relief as set forth in Subtitle G § 409.1. As the Repairs meet the special exception standards in Subtitle X § 901.2 and are not subject to the provisions and limitations of Subtitle G § 1201.1 *et. seq*, as more fully explained below, the Applicant's request for relief should be granted.

Pursuant to D.C. Code  $\S$  6-641.07(g)(2) and 11 DCMR Subtitle X  $\S$  901.2, the Board is authorized to grant a special exception where it finds the special exception:

- (1) Will be in harmony with the general purpose and intent of the Zoning Regulations and Zoning Maps;
- (2) Will not tend to affect adversely, the use of neighboring property in accordance with the Zoning Regulations and Zoning Maps; and
- (3) Subject in specific cases to special conditions specified in the Zoning Regulations. 11 DCMR Subtitle X § 901.2.

Relief granted through a special exception is presumed appropriate, reasonable, and compatible with other uses in the same zoning classification, provided the specific requirements for the relief are met. In reviewing an application for special exception relief, "[t]he Board's discretion . . . is limited to a determination of whether the exception sought meets the requirements of the regulation." *First Baptist Church of Wash. v. District of Columbia Bd. of Zoning Adjustment*, 432 A.2d 695, 701 (D.C. 1981) (quoting *Stewart v. District of Columbia Bd. of Zoning Adjustment*, 305 A.2d 516, 518 (D.C. 1973)). If an applicant meets its burden, the Board must ordinarily grant the application. *Id.* 

#### V. APPLICANT MEETS BURDEN FOR SPECIAL EXCEPTION RELIEF

## A. The Relief is Harmonious with the General Purpose and Intent of the Zoning Regulations and Maps

The special exception relief will be in harmony with the purpose and intent of the Zoning Regulations and related maps. The Property is located in the MU-4 Zone, a mixed-used zone intended to be applied throughout the city consistent with the density designation of the Comprehensive Plan. The purpose of that Zone is to: (a) [p]ermit moderate-density mixed-use development; (b) [p]rovide facilities for shopping and business needs, housing, and mixed uses for large segments of the District of Columbia outside of the central core; and (c) [b]e located in low-and moderate-density residential areas with access to main roadways or rapid transit stops, and include office employment centers, shopping centers, and moderate bulk mixed-use centers. *See* Subtitle G § 400.3.

The Repairs are compatible with the purpose of the MU-4 Zone as they will permit office, retail and gym/exercise studio uses within an existing historic three-story building, exactly the kind of "moderate-density mixed use development" envisioned by the special exception standard. Subtitle G § 400.3(a). The Repairs are necessary in order to accommodate multiple uses at the Building and to provide tenants with disparate expectations and requirements for ingress and egress. The Repairs will permit two of the three explicitly identified uses (shopping and business needs) in Subtitle G § 400.3(b). Finally, the Property is located on a high-traffic mixed-use corridor at the entrance to Georgetown, adjacent to a number of high-frequency bus routes. Subtitle G § 400.3(c). Accordingly, the requested relief is harmonious with the purpose and intent of the Zoning Regulations.

#### B. The Relief will not tend to Adversely Affect the Use of Neighboring Property

The Repairs will not adversely affect adjacent properties. The adjacent properties are 2809 M Street, NW (the "2809 Property") and 1210 28th Street, NW (the "1210 Property"). The 2809 Property also faces M Street, NW with primary ingress and egress from M Street, NW. The Repairs will be located entirely on the Property and will not impede access to the 2809 Property through the open setback running between the Property and the 1210 Property. Like the entrance to the 1210 Property, the Repairs will serve as a raised entrance to an existing Building. While the Repairs will be visible from the 1210 Property, they will be shorter than the existing height of the Property and their open design will have a de minimis effect on light and air's ability to reach the 1210 Property.

#### C. The Repairs Satisfy the Special Conditions of Subtitle G § 1201.1 et. seq.

In addition to the general special exception standard, relief from the rear yard requirements shall be provided if the proposal meets the provisions of Subtitle G § 1201.1 *et. seq.*. The applicable provisions are as follows:

1. No apartment window shall be located within forty feet (40 ft.) directly in front of another building. Subtitle  $G \S 1201.1(a)$ 

The Building will exclusively be used for office, retail and mercantile uses, so this section does not apply to the Repairs.

- 2. No office window shall be located within thirty feet (30 ft.) directly in front of another office window, nor eighteen feet (18 ft.) in front of a blank wall. Subtitle G § 1201.1(b)

  The Building envelope is being restored to its historic appearance with no change in fenestration. The rear yard relief requested will not alter any fenestration.
- 3. In buildings that are not parallel to the adjacent buildings, the angle of sight lines and the distance of penetration of sight lines into habitable rooms shall be considered in determining distances between windows and appropriate yards. Subtitle G § 1201.1(c)

The sight lines of the Building are not changing as a result of the Repairs. The Repairs will provide a secondary stair with a limited use.

4. Provision shall be included for service functions, including parking and loading access and adequate loading areas. Subtitle  $G \S 1201.1(d)$ 

The Repairs are a minor addition to the existing Building, the Building is not being altered, except to restore it to its historic appearance prior to the crash. There will therefore be no impact on parking or loading. Note that the change in use proposed by the renovations that includes the Repairs does not trigger parking minimums as the property is historic and an expansion is not part of the proposed renovations. *See* Subtitle C § 705.3. The Repairs

will therefore have no impact on the provision of required parking and loading at the Property.

5. Upon receiving an application to waive rear yard requirements in the subject zone, the Board of Zoning Adjustment shall submit the application to the Office of Planning for coordination, review, report, and impact assessment, along with reviews in writing from all relevant District of Columbia departments and agencies, including the Department of Transportation, the District of Columbia Housing Authority and, if a historic district or historic landmark is involved, the Historic Preservation Office. Subtitle G § 1201.1(e)

The Applicant has already appeared before and received approval from the Historic Preservation Review Board in Case No. HPA 19-073 and the Old Georgetown Board in Case No. OG 19-029. To the extent further cooperation is required, the Applicant will cooperate with and work alongside the Department of Transportation, the Historic Preservation Office and other District of Columbia departments and agencies having jurisdiction over the Property.

The conditions of Subtitle G § 1201.1 *et. seq.* which would prohibit a special exception for rear yard relief are broadly inapplicable to the Repairs, the Building and the Property. The existing and proposed uses for the Property and the existing uses at the 2809 Property, and the 1210 Property are all compatible with relief from the rear yard requirements. The Building's layout and size similarly make the Repairs an ideal candidate for rear yard relief.

#### VI. <u>COMMUNITY OUTREACH</u>

The Applicant will attend meetings of Advisory Neighborhood Commission (ANC) 2E06 to introduce the application and discuss the Repairs. The Applicant will formally present the application to ANC 2E06 at its next available public meeting.

#### VII. <u>CONCLUSION</u>

For the reasons stated above, the Repairs meet the applicable standards for special exception relief under the Zoning Regulations. Accordingly, the Applicant respectfully requests the Board grant the application.

Respectfully Submitted,

COZEN O'CONNOR

Meridith H. Moldenhauer

Harrison Haas


1200 19th Street NW

Washington, DC 20036

#### Tab A



Tab B



[

#### Tab C

# ALTERATIONS AND REPAIRS AT 2805 M ST, NW

B - OFFICE/RETAIL

M - MERCANTILE

HIGHRISE: NO

**CONSTRUCTION TYPE:** 

NUMBER OF STORIES: 3

COVERED MALL: NO

FIRE ALARM SYSTEM: NO

ADA ACCESSIBILITY: NO

**EMERGENCY POWER: NO** 

**EGRESS LOADS:** 

OCCUPANCIES ARE UNCHANGED.

BUILDING - TYPE IIIB, NOT SPRINKLED

2805 M STREET, NW WASHINGTON, DC 2007

BBGM Project Number 1123.00

# BZA APPLICATION

# 02.09.2021

## Washington, D.C., 20009

## **SCOPE OF WORK:**

LIGHTING AND DEVICES (RECEPTACLES, SWITCHES, ETC.) IN KIND; REPLACEMENT OF MECHANICAL EQUIPMENT IN KIND; AND PROVIDING SECURITY

## **BUILDING CODES** - (Washington D.C.)

BUILDING- INTERNATIONAL EXISTING BUILDING CODE (IEBC) 2012 INTERNATIONAL BUILDING CODE (IBC) 2012 DC BUILDING CODE (DCBC) 2013 DCMR 12A BUILDING CODE SUPPLEMENT 2013 DC EXISTING BUILDING CODE 2013 DCMA 12J EXISTING BUILDING CODE 2013

MECHANICAL- INTERNATIONAL MECHANICAL CODE (IMC) 2012 DC MECHANICAL CODE 2013 DCMR 12E 2013 MECHANICAL CODE SUPPLEMENT

PLUMBING- INTERNATIONAL PLUMBING CODE (IPC) 2012 [REF. 12 DCMR F DC PLUMBING CODE 2013 DCMR 12F 2013 PLUMBIND CODE SUPPLEMENT

GAS- INTERNATIONAL FUEL GAS CODE (IFGC) 2012

ELECTRICAL- NATIONAL ELECTRICAL CODE (NEC - NFPA 70, 2011 EDITION) DC ELECTRICAL CODE 1013 DCMR 12C 2013 ELECTRICAL CODE SUPPLEMENT

ENERGY- INTERNATIONAL ENERGY CONSERVATION CODE (IECC) 2012 DC ENERGY CONSERVATION CODE 2013 DCMR 12 2013 ENERGY CONSERVATION CODE SUPPLEMENT

FIRE PREVENTION- NATIONAL FIRE PROTECTION ASSOCIATION (NFPA) 2012 LIFE SAFETY- LIFE SAFETY CODE (LSC) 101 2012

ACCESSIBILITY-2010 ADA STANDARDS FOR ACCESSIBLE DESIGN INTERNATIONAL BUILDING CODE (IBC) 2012 2009 ANSI A117.1 DCMR 12A BUILDING CODE SUPPLEMENT

ELEVATOR CODE- INTERNATIONAL BUILDING CODE (IBC) 2012 ASME A17.1/CSA B44 OTHER CODES-DC GREEN BUILDING ACT OF 2006 DC GREEN CONSTURCTION CODE 2013 INTERNATIONAL GREEN CONSTRUCTION CODE 2012 DCMR 12K 2013 GREEN CONSTRUCTION CODE SUPPLEMENT DC PROPERTY MAINTENANCE CODE 2013 INTERNATIONAL PROPERTY MAINTENANCE CODE 2012

DCMR 12G 2013 PROPERTY MAINTENANCE CODE SUPPLEMENT

LOTS: 0201


ZONE: MU-4 HEIGHT: 32' - 6"

SQUARE: 1212

STORIES: 3 ABOVE GRADE + BASEMENT SITE AREA: 5,130 SQ.FT.

HISTORIC: GEORGETOWN USES: OFFICE/RETAIL

## **VICINITY MAP**







BBGM 1825 K Street, NW suite 300 Washington, DC 20006

Tel. 202.452.1644 Fax. 202.452.1647

**CONSULTANT: CHRISTIE DESIGN GROUP** 


912 THAYER AVE, STE 300 SILVER SPRING, MD 20910

OFFICE: (301)608-0005 STRUCTURAL: STRUCTURA INC.


12358 Parklawn Drive, Suite #140 North Bethesda, MD, 20852

(301) 987-9234

Caitlin Mueller, PE cmueller@structura-inc.com 240.477.1882








## OCCUPANCY INFORMATION


Original Address	Bay Reference	Specific Location		Use					Certificate o	f Occupancy	
		Level	Portion	Current	Proposed	AREA	SQ.FT. PER PERSON	OCCUPANCY LOAD	CofO #	Date Issued	
	#1	Basement	All	Office - B	No Change	2,640	100 SQ.FT.	26	B172760	9/7/95	
		1st	Partial	Office - B	Mercantile - M	2,664	30 SQ.FT.	88	CO1500318	11/3/14	
2001			Partial	Office - B					B174297	3/28/96	
2801			Partial						B172760	9/7/95	
		2nd	All	Office - B	No Change	1,316	100 SQ.FT.	13			
		3rd / Loft	All			837	100 SQ.FT.	8			
	#2	Basement	All	Office - B	No Change	2,640	100 SQ.FT.	26	B172760	9/7/95	
			Partial	Office - B			ı .	CO1500318	11/3/14		
2002		42	1st	Partial	Office - B	Mercantile - M 2,66	2,664	30 SQ.FT.	88	B174297	3/28/96
2803			Partial					[	B172760	9/7/95	
		2nd	All	Office - B	No Change	1,316	100 SQ.FT.	13			
		3rd / Loft	All			837	100 SQ.FT.	8			
2805	#3	Basement	All		No Change	NIC			CO1702540	5/31/17	
		1st	All	Fast Food A-2			N.I.C	N.I.C			
		2nd	All	Gym or Exercise Studio	No Change	3,843	50 SQ.FT.	77	CO1302977	8/22/13	

## EGRESS INFORMATION




6. ROOF CONSTRUCTION: 0 HOURS


7. DEMISING WALL: 0 HOURS







2 LIFE SAFETY PLAN - SECOND FLOOR
A003 3/32" = 1'-0"



1 LIFE SAFETY PLAN - FIRST FLOOR
A003 3/32" = 1'-0"

OWNER

2805 BOND ST. EQUITIES, LLC
BRIAN FRIEDMAN
2805 M STREET, NW
WASHINGTON, DC 20007

## **CONSULTANTS**

202-271-4200

MEP:
CHRISTIE DESIGN GROUP
912 THAYER AVE, STE 300,
SILVER SPRING, MD 20910
OFFICE: (301)608-0005

STRUCTURAL:
STRUCTURA INC.
12358 Parklawn Drive, Suite #140
North Bethesda, MD, 20852
(301) 987-9234
Caitlin Mueller, PE
cmueller@structura-inc.com
240.477.1882

SUBMISSIONS

Date Description

02.09.2021 BZA APPLICATION

**REVISIONS** 

No. Date Descr

BBGN

1825 K Street NW Suite 300 Washington DC 20006 Tel 202 452 1644 Fax 202 452 1647 www.bbgm.com

This document and the ideas and designs incorporated within it are


instruments of Professional Service. They are and remain the property of BBGM/Architects & Interiors, Inc. (BBGM) and are not to be used or reproduced in whole or in part for another project without the express written consent of BBGM. Unauthorized additions to or alterations of this document, or to related construction, are prohibited. These drawings are protected by copyright. © 2014 BBGM/Architects & Interiors, Inc.

PROJECT

ALTERATIONS AND REPAIRS AT 2805 M ST, NW

2805 M STREET, NW WASHINGTON, DC 2007

LIFE SAFETY PLAN





Existing Side 2801 M St.

Existing wood stair to be removed

- Existing side stair to remain, replace broken pickets to match existing


Basement window well area to remain as is



Existing Side/Rear 2805 M St.

The banner and marketing signs removed

Remove bracket sign at the corner



Existing Front/Rear 2805 M St.



1825 K Street NW Suite 300 Washington DC 20006 Tel 202 452 1644 Fax 202 452 1647 www.bbgm.com

2805 BOND ST. EQUITIES, LLC

BRIAN FRIEDMAN 2805 M STREET, NW WASHINGTON, DC 20007

**CONSULTANTS** 

STRUCTURAL: STRUCTURA INC.

(301) 987-9234

240.477.1882

SUBMISSIONS

CHRISTIE DESIGN GROUP 912 THAYER AVE, STE 300, SILVER SPRING, MD 20910 OFFICE: (301)608-0005

12358 Parklawn Drive, Suite #140 North Bethesda, MD, 20852

Caitlin Mueller, PE cmueller@structura-inc.com

202-271-4200


This document and the ideas and designs incorporated within instruments of Professional Service. They are and remain the proper BBGM/Architects & Interiors, Inc. (BBGM) and are not to be use reproduced in whole or in part for another project without the exwritten consent of BBGM. Unauthorized additions to or alterations of document, or to related construction, are prohibited. These drawing protected by copyright. © 2014 BBGM/Architects & Interiors, Inc.


PROJECT

ALTERATIONS AND REPAIRS AT 2805 M ST, NW

2805 M STREET, NW WASHINGTON, DC 2007

EXISTING EXTERIOR IMAGES





OWNER

2805 BOND ST. EQUITIES, LLC
BRIAN FRIEDMAN
2805 M STREET, NW
WASHINGTON, DC 20007
202-271-4200

**CONSULTANTS** 

CHRISTIE DESIGN GROUP
912 THAYER AVE, STE 300,
SILVER SPRING, MD 20910
OFFICE: (301)608-0005

STRUCTURAL:
STRUCTURA INC.
12358 Parklawn Drive, Suite #140
North Bethesda, MD, 20852
(301) 987-9234
Caitlin Mueller, PE
cmueller@structura-inc.com
240.477.1882

SUBMISSIONS

Date Description

02.09.2021 BZA APPLICATION

REVISIONS

No. Date Descri

No. Date Descript

1825 K Street NW Suite 300 Washington DC 20006
Tel 202 452 1644 Fax 202 452 1647 www.bbgm.com


This document and the ideas and designs incorporated within it are instruments of Professional Service. They are and remain the property of BBGM/Architects & Interiors, Inc. (BBGM) and are not to be used or reproduced in whole or in part for another project without the express written consent of BBGM. Unauthorized additions to or alterations of this document, or to related construction, are prohibited. These drawings are protected by copyright. © 2014 BBGM/Architects & Interiors, Inc.


PROJECT

ALTERATIONS AND REPAIRS AT 2805 M ST, NW

2805 M STREET, NW WASHINGTON, DC 2007

EXISTING FIRST FLOOR PLAN





2805 BOND ST. EQUITIES, LLC
BRIAN FRIEDMAN
2805 M STREET, NW
WASHINGTON, DC 20007
202-271-4200

**CONSULTANTS** 

CHRISTIE DESIGN GROUP
912 THAYER AVE, STE 300,
SILVER SPRING, MD 20910
OFFICE: (301)608-0005

STRUCTURAL:
STRUCTURA INC.
12358 Parklawn Drive, Suite #140
North Bethesda, MD, 20852
(301) 987-9234
Caitlin Mueller, PE
cmueller@structura-inc.com
240.477.1882

SUBMISSIONS

Date Description

02.09.2021 BZA APPLICATION

REVISIONS

No. Date Descri

BBGM

1825 K Street NW Suite 300 Washington DC 20006

This document and the ideas and designs incorporated within it are instruments of Professional Service. They are and remain the property of BBGM/Architects & Interiors, Inc. (BBGM) and are not to be used or reproduced in whole or in part for another project without the express written consent of BBGM. Unauthorized additions to or alterations of this document, or to related construction, are prohibited. These drawings are protected by copyright. © 2014 BBGM/Architects & Interiors, Inc.


Tel 202 452 1644 Fax 202 452 1647 www.bbgm.com


PROJECT

ALTERATIONS AND REPAIRS AT 2805 M ST, NW

2805 M STREET, NW WASHINGTON, DC 2007

EXISTING SECOND FLOOR PLAN





1 EXISTING LOFT FLOOR PLAN
A008 1/4" = 1'-0"



OWNER

2805 BOND ST. EQUITIES, LLC
BRIAN FRIEDMAN
2805 M STREET, NW
WASHINGTON, DC 20007

**CONSULTANTS** 

**SUBMISSIONS** 

**REVISIONS** 

02.09.2021 BZA APPLICATION

202-271-4200

CHRISTIE DESIGN GROUP
912 THAYER AVE, STE 300,
SILVER SPRING, MD 20910
OFFICE: (301)608-0005

STRUCTURAL:
STRUCTURA INC.
12358 Parklawn Drive, Suite #140
North Bethesda, MD, 20852
(301) 987-9234
Caitlin Mueller, PE
cmueller@structura-inc.com
240.477.1882

1825 K Street NW Suite 300 Washington DC 20006
Tel 202 452 1644 Fax 202 452 1647 www.bbgm.com

This document and the ideas and designs incorporated within it are instruments of Professional Service. They are and remain the property of

BBGM/Architects & Interiors, Inc. (BBGM) and are not to be used or reproduced in whole or in part for another project without the express written consent of BBGM. Unauthorized additions to or alterations of this document, or to related construction, are prohibited. These drawings are protected by copyright. © 2014 BBGM/Architects & Interiors, Inc.


PROJECT

ALTERATIONS AND REPAIRS AT 2805 M ST, NW

2805 M STREET, NW WASHINGTON, DC 2007

EXISTING LOFT FLOOR PLAN





1 EXISTING EXTERIOR SECTION VIEW
A009 1/4" = 1'-0"

2805 BOND ST. EQUITIES, LLC BRIAN FRIEDMAN 2805 M STREET, NW WASHINGTON, DC 20007

**CONSULTANTS** 

202-271-4200

CHRISTIE DESIGN GROUP 912 THAYER AVE, STE 300, SILVER SPRING, MD 20910 OFFICE: (301)608-0005 STRUCTURAL: STRUCTURA INC. 12358 Parklawn Drive, Suite #140 North Bethesda, MD, 20852 (301) 987-9234
Caitlin Mueller, PE
cmueller@structura-inc.com
240.477.1882

**SUBMISSIONS** Date Description 02.09.2021 BZA APPLICATION

**REVISIONS** 

1825 K Street NW Suite 300 Washington DC 20006 Tel 202 452 1644 Fax 202 452 1647 www.bbgm.com


instruments of Professional Service. They are and remain the property of BBGM/Architects & Interiors, Inc. (BBGM) and are not to be used or reproduced in whole or in part for another project without the express written consent of BBGM. Unauthorized additions to or alterations of this document, or to related construction, are prohibited. These drawings are protected by copyright. © 2014 BBGM/Architects & Interiors, Inc.


This document and the ideas and designs incorporated within it are

ALTERATIONS AND REPAIRS AT 2805 M ST, NW

2805 M STREET, NW WASHINGTON, DC 2007


**EXISTING BUILDING SECTION** 





FOR FATAS

EXISTING CONDITIONS DWG SUBMITTED PER REQUEST OF OGB/ CFA DOES NOT CHANGE SCOPE OF WORK.



Tel 202 452 1644 Fax 202 452 1647 www.bbgm.com

instruments of Professional Service. They are and remain the property of


BBGM/Architects & Interiors, Inc. (BBGM) and are not to be used or reproduced in whole or in part for another project without the express written consent of BBGM. Unauthorized additions to or alterations of this document, or to related construction, are prohibited. These drawings are protected by copyright. © 2014 BBGM/Architects & Interiors, Inc.

ALTERATIONS AND REPAIRS AT 2805 M ST, NW

2805 M STREET, NW WASHINGTON, DC 2007

**EXISTING EXTERIOR ELEVATIONS** 

3 EXISTING EXTERIOR SIDE ELEVATION - 28TH ST 1/4" = 1'-0"



2. G.C. TO PATCH, SPACKLE AND SAND, REPAIR AND PREP ALL EXISTING WALLS AND FLOORS AND PREPARE SURFACE TO RECEIVE NEW FINISHES.

3. G.C. TO COMPLY WITH ALL BUILDING RULES AND REGULATIONS FOR NEW CONSTRUCTION.

4. G.C. TO VERIFY ALL EXISTING CONDITIONS AND CONFIRM WITH ARCHITECT LOCATIONS OF ALL CHALK LINES PRIOR TO ANY CONSTRUCTION.

5. G.C. TO CONSULT WITH ARCHITECT PRIOR TO INSTALLATION OF FIRE SIGNALING DEVICES.

6. MAINTAIN A MIN. OF 44" CLEARANCE AT EGRESS CORRIDORS.

1. ALL DOORS THAT ARE NOT LABELED ARE EXISTING TO REMAIN.

7. DIMENSIONS AND ALIGNMENTS ARE FROM FACE TO FINISH TO FACE OF FINISH. PROVIDE FURRING AS REQUIRED TO ACHIEVE ALIGNMENTS SHOWN.

8. LOCATE DOORS 4" FROM FACE TO INSIDE CORNER OF PARTITION TO DOOR AND 8" FROM OUTSIDE CORNER OF PARTITION TO DOOR, U.O.N. LOCATED DOORS WITH CLOSERS NO LESS THAN 1'-6" TO EDGE OF DOOR AT PULL SIDE AND 1'-0" TO EDGE OF DOOR AT PUSH-SIDE.

9. VERIFY DIMENSIONS NOTED "CLEAR", "HOLD", "MIN", OR "V.I.F." NOTIFY ARCHITECT OF DISCREPANCIES PRIOR TO PROCEEDING.

10. FIRESAFE ALL FLOOR OPENINGS AS REQUIRED. WHERE PENETRATIONS OCCUR AT RATED ENCLOSURES MAINTAIN CONTINUITY OF RATING AS REQUIRED.

11. REFER TO MEP DRAWINGS FOR ALL POWER/COMMUNICATION, HVAC AND LIGHTING SPECS.

12. G.C. TO THOROUGHLY CLEAN EXISTING AREAS, AND FILL AND REPAIR ALL DAMAGED AREAS AS REQUIRED.

- 1) INSTALL NEW EGRESS STAIR (PER PRIOR CFA APPROVAL, DATED 06/21/19). (REFER TO STRUCTURAL DRAWINGS FOR SPECIFICATIONS).
- 2 INSTALL NEW WINDOWS (PER PRIOR CFA APPROVAL, DATED 06/21/19).
- 3 REPLACE PLUMBING FIXTURES AT RESTROOMS IN EXISTING LOCATIONS IN KIND. (REFER TO MEP DRAWINGS FOR SPECIFICATIONS).
- 4 REPLACE EXISTING LIGHTING AND DEVICES (RECEPTACLES, SWITCHES, ETC.) IN EXISTING LOCATIONS IN KIND. (REFER TO MEP DRAWINGS FOR SPECIFICATIONS).
- (5) REPLACE MECHANICAL EQUIPMENT IN EXISTING LOCATIONS. (REFER TO MEP DRAWINGS FOR SPECIFICATIONS).
- 6 PERFORM STRUCTURAL MODIFICATIONS DUE TO PARTIAL CHANGE OF USE (OFFICE TO RETAIL). (REFER TO STRUCTURAL DRAWINGS).
- 7 PROVIDE SECURITY ALARM UPGRADES. (REFER TO MEP DRAWINGS).
- (8) REINSTALL DRYWALL AND INSULATION AT EXISTING FRAMING DUE TO PRIOR REPAIRS AND MOLD ABATEMENT

2805 BOND ST. EQUITIES, LLC
BRIAN FRIEDMAN
2805 M STREET, NW

**WASHINGTON, DC 20007** 

**CONSULTANTS** 

202-271-4200

CHRISTIE DESIGN GROUP
912 THAYER AVE, STE 300,
SILVER SPRING, MD 20910
OFFICE: (301)608-0005

STRUCTURAL:
STRUCTURA INC.
12358 Parklawn Drive, Suite #140
North Bethesda, MD, 20852
(301) 987-9234
Caitlin Mueller, PE

cmueller@structura-inc.con

240.477.1882

**SUBMISSIONS** 



This document and the ideas and designs incorporated within it are instruments of Professional Service. They are and remain the property of BBGM/Architects & Interiors, Inc. (BBGM) and are not to be used or reproduced in whole or in part for another project without the express written consent of BBGM. Unauthorized additions to or alterations of this


protected by copyright. © 2014 BBGM/Architects & Interiors, Inc.


PROJECT

ALTERATIONS AND REPAIRS AT 2805 M ST, NW

2805 M STREET, NW WASHINGTON, DC 2007

FIRST FLOOR PLAN





AREA OF WORK

AREA NOT IN SCOPE

**KEY LEGEND:** 

1 CONSTRUCTION - SECOND FLOOR PLAN
A104 1/4" = 1'-0"

# z

## **CONSTRUCTION - GENERAL NOTES**

- 1. ALL DOORS THAT ARE NOT LABELED ARE EXISTING TO REMAIN.
- 2. G.C. TO PATCH, SPACKLE AND SAND, REPAIR AND PREP ALL EXISTING WALLS AND FLOORS AND PREPARE SURFACE TO RECEIVE NEW FINISHES.
- 3. G.C. TO COMPLY WITH ALL BUILDING RULES AND REGULATIONS FOR NEW CONSTRUCTION.
- 4. G.C. TO VERIFY ALL EXISTING CONDITIONS AND CONFIRM WITH ARCHITECT LOCATIONS OF ALL CHALK LINES PRIOR TO ANY CONSTRUCTION.
- 5. G.C. TO CONSULT WITH ARCHITECT PRIOR TO INSTALLATION OF FIRE SIGNALING DEVICES.
- 6. MAINTAIN A MIN. OF 44" CLEARANCE AT EGRESS CORRIDORS.
- 7. DIMENSIONS AND ALIGNMENTS ARE FROM FACE TO FINISH TO FACE OF FINISH. PROVIDE FURRING AS REQUIRED TO ACHIEVE ALIGNMENTS SHOWN.
- 8. LOCATE DOORS 4" FROM FACE TO INSIDE CORNER OF PARTITION TO DOOR AND 8" FROM OUTSIDE CORNER OF PARTITION TO DOOR, U.O.N. LOCATED DOORS WITH CLOSERS NO LESS THAN 1'-6" TO EDGE OF DOOR AT PULL SIDE AND 1'-0" TO EDGE OF DOOR AT PUSH-SIDE.
- 9. VERIFY DIMENSIONS NOTED "CLEAR", "HOLD", "MIN", OR "V.I.F." NOTIFY ARCHITECT OF DISCREPANCIES PRIOR TO PROCEEDING.
- 10. FIRESAFE ALL FLOOR OPENINGS AS REQUIRED. WHERE PENETRATIONS OCCUR AT RATED ENCLOSURES MAINTAIN CONTINUITY OF RATING AS REQUIRED.
- 11. REFER TO MEP DRAWINGS FOR ALL POWER/COMMUNICATION, HVAC AND LIGHTING SPECS.
- 12. G.C. TO THOROUGHLY CLEAN EXISTING AREAS, AND FILL AND REPAIR ALL DAMAGED AREAS AS REQUIRED.

## **CONSTRUCTION PLAN NOTES**

- 1) INSTALL NEW EGRESS STAIR (PER PRIOR CFA APPROVAL, DATED 06/21/19). (REFER TO STRUCTURAL DRAWINGS FOR SPECIFICATIONS).
- 2 INSTALL NEW WINDOWS (PER PRIOR CFA APPROVAL, DATED 06/21/19).
- (3) REPLACE PLUMBING FIXTURES AT RESTROOMS IN EXISTING LOCATIONS IN KIND. (REFER TO MEP DRAWINGS FOR SPECIFICATIONS).
- 4 REPLACE EXISTING LIGHTING AND DEVICES (RECEPTACLES, SWITCHES, ETC.) IN EXISTING LOCATIONS IN KIND. (REFER TO MEP DRAWINGS FOR SPECIFICATIONS).
- (5) REPLACE MECHANICAL EQUIPMENT IN EXISTING LOCATIONS. (REFER TO MEP DRAWINGS FOR SPECIFICATIONS).
- 6 PERFORM STRUCTURAL MODIFICATIONS DUE TO PARTIAL CHANGE OF USE (OFFICE TO RETAIL). (REFER TO STRUCTURAL DRAWINGS).
- 7 PROVIDE SECURITY ALARM UPGRADES. (REFER TO MEP DRAWINGS).
- 8 REINSTALL DRYWALL AND INSULATION AT EXISTING FRAMING DUE TO PRIOR REPAIRS AND MOLD ABATEMENT.

BRIAN FRIEDMAN 2805 M STREET, NW WASHINGTON, DC 20007 202-271-4200

2805 BOND ST. EQUITIES, LLC

CONSULTANTS

CHRISTIE DESIGN GROUP
912 THAYER AVE, STE 300,
SILVER SPRING, MD 20910
OFFICE: (301)608-0005

STRUCTURAL:
STRUCTURA INC.
12358 Parklawn Drive, Suite #140
North Bethesda, MD, 20852
(301) 987-9234
Caitlin Mueller, PE

cmueller@structura-inc.con

240.477.1882

**SUBMISSIONS** 



25 K Street NW Suite 300 Washington DC 20006 202 452 1644 Fax 202 452 1647 www.bbgm.com


instruments of Professional Service. They are and remain the property of BBGM/Architects & Interiors, Inc. (BBGM) and are not to be used or reproduced in whole or in part for another project without the express written consent of BBGM. Unauthorized additions to or alterations of this document, or to related construction, are prohibited. These drawings are protected by copyright. © 2014 BBGM/Architects & Interiors, Inc.


PROJECT

ALTERATIONS AND REPAIRS AT 2805 M ST, NW

2805 M STREET, NW WASHINGTON, DC 2007

SECOND FLOOR PLAN





AREA OF WORK

AREA NOT IN SCOPE

KEY LEGEND:

1 CONSTRUCTION - LOFT FLOOR PLAN
1/4" = 1'-0"

# z

## **CONSTRUCTION - GENERAL NOTES**

- 1. ALL DOORS THAT ARE NOT LABELED ARE EXISTING TO REMAIN.
- 2. G.C. TO PATCH, SPACKLE AND SAND, REPAIR AND PREP ALL EXISTING WALLS AND FLOORS AND PREPARE SURFACE TO RECEIVE NEW FINISHES.
- 3. G.C. TO COMPLY WITH ALL BUILDING RULES AND REGULATIONS FOR NEW CONSTRUCTION.
- 4. G.C. TO VERIFY ALL EXISTING CONDITIONS AND CONFIRM WITH ARCHITECT LOCATIONS OF ALL CHALK LINES PRIOR TO ANY CONSTRUCTION.
- 5. G.C. TO CONSULT WITH ARCHITECT PRIOR TO INSTALLATION OF FIRE SIGNALING DEVICES.
- 6. MAINTAIN A MIN. OF 44" CLEARANCE AT EGRESS CORRIDORS.
- 7. DIMENSIONS AND ALIGNMENTS ARE FROM FACE TO FINISH TO FACE OF FINISH. PROVIDE FURRING AS REQUIRED TO ACHIEVE ALIGNMENTS SHOWN.
- 8. LOCATE DOORS 4" FROM FACE TO INSIDE CORNER OF PARTITION TO DOOR AND 8" FROM OUTSIDE CORNER OF PARTITION TO DOOR, U.O.N. LOCATED DOORS WITH CLOSERS NO LESS THAN 1'-6" TO EDGE OF DOOR AT PULL SIDE AND 1'-0" TO EDGE OF DOOR AT PUSH-SIDE.
- 9. VERIFY DIMENSIONS NOTED "CLEAR", "HOLD", "MIN", OR "V.I.F." NOTIFY ARCHITECT OF DISCREPANCIES PRIOR TO PROCEEDING.
- 10. FIRESAFE ALL FLOOR OPENINGS AS REQUIRED. WHERE PENETRATIONS OCCUR AT RATED ENCLOSURES MAINTAIN CONTINUITY OF RATING AS REQUIRED.
- 11. REFER TO MEP DRAWINGS FOR ALL POWER/COMMUNICATION, HVAC AND LIGHTING SPECS.
- 12. G.C. TO THOROUGHLY CLEAN EXISTING AREAS, AND FILL AND REPAIR ALL DAMAGED AREAS AS REQUIRED.

## **CONSTRUCTION PLAN NOTES**

- 1) INSTALL NEW EGRESS STAIR (PER PRIOR CFA APPROVAL, DATED 06/21/19). (REFER TO STRUCTURAL DRAWINGS FOR SPECIFICATIONS).
- 2 INSTALL NEW WINDOWS (PER PRIOR CFA APPROVAL, DATED 06/21/19).
- 3 REPLACE PLUMBING FIXTURES AT RESTROOMS IN EXISTING LOCATIONS IN KIND. (REFER TO MEP DRAWINGS FOR SPECIFICATIONS).
- 4 REPLACE EXISTING LIGHTING AND DEVICES (RECEPTACLES, SWITCHES, ETC.) IN EXISTING LOCATIONS IN KIND. (REFER TO MEP DRAWINGS FOR SPECIFICATIONS).
- (5) REPLACE MECHANICAL EQUIPMENT IN EXISTING LOCATIONS. (REFER TO MEP DRAWINGS FOR SPECIFICATIONS).
- 6 PERFORM STRUCTURAL MODIFICATIONS DUE TO PARTIAL CHANGE OF USE (OFFICE TO RETAIL). (REFER TO STRUCTURAL DRAWINGS).
- 7 PROVIDE SECURITY ALARM UPGRADES. (REFER TO MEP DRAWINGS).
- 8 REINSTALL DRYWALL AND INSULATION AT EXISTING FRAMING DUE TO PRIOR REPAIRS AND MOLD ABATEMENT.


2805 BOND ST. EQUITIES, LLC
BRIAN FRIEDMAN
2805 M STREET, NW
WASHINGTON, DC 20007

## **CONSULTANTS**

202-271-4200

CHRISTIE DESIGN GROUP
912 THAYER AVE, STE 300,
SILVER SPRING, MD 20910
OFFICE: (301)608-0005

STRUCTURAL:
STRUCTURA INC.
12358 Parklawn Drive, Suite #140
North Bethesda, MD, 20852
(301) 987-9234
Caitlin Mueller, PE
cmueller@structura-inc.com
240.477.1882



**SUBMISSIONS** 

25 K Street NW Suite 300 Washington DC 20006 202 452 1644 Fax 202 452 1647 www.bbgm.com

BBGM/Architects & Interiors, Inc. (BBGM) and are not to be used or reproduced in whole or in part for another project without the express written consent of BBGM. Unauthorized additions to or alterations of this document, or to related construction, are prohibited. These drawings are protected by copyright. © 2014 BBGM/Architects & Interiors, Inc.

This document and the ideas and designs incorporated within it are


PROJECT


ALTERATIONS AND REPAIRS AT 2805 M ST, NW


2805 M STREET, NW

WASHINGTON, DC 2007

LOFT PLAN









PAINT	APPLICAITON
DECORATOR'S WHITE: OC-149	BRICK
METROPOLITAN: AF-690	WINDOWS
KENDALL CHARCOAL: HC-166	SHUTTERS
BLACK IRON: 2120	BALCONY
OLD NAVY: 2063-10	DOORS

**SUBMISSIONS** Date Description 02.09.2021 BZA APPLICATION

2805 BOND ST. EQUITIES, LLC

BRIAN FRIEDMAN 2805 M STREET, NW **WASHINGTON, DC 20007** 

**CONSULTANTS** 

**CHRISTIE DESIGN GROUP** 

912 THAYER AVE, STE 300, SILVER SPRING, MD 20910

12358 Parklawn Drive, Suite #140

North Bethesda, MD, 20852

OFFICE: (301)608-0005

STRUCTURAL:

(301) 987-9234 Caitlin Mueller, PE cmueller@structura-inc.com

240.477.1882

STRUCTURA INC.

202-271-4200

**REVISIONS** 



Tel 202 452 1644 Fax 202 452 1647 www.bbgm.com

instruments of Professional Service. They are and remain the property of BBGM/Architects & Interiors, Inc. (BBGM) and are not to be used or reproduced in whole or in part for another project without the express written consent of BBGM. Unauthorized additions to or alterations of this document, or to related construction, are prohibited. These drawings are protected by copyright. © 2014 BBGM/Architects & Interiors, Inc.

PROJECT


ALTERATIONS AND REPAIRS AT 2805 M ST, NW


2805 M STREET, NW WASHINGTON, DC 2007

**EXTERIOR ELEVATIONS** 



- EXISTING FIXTURES TO REMAIN PROJECT No.: 1123.00 3 **EXTERIOR SIDE ELEVATION - 28TH ST**A201 1/4" = 1'-0" A201 **EXTERIOR SIDE ELEVATION - 28TH ST** 





**OWNER** 

2805 BOND ST. EQUITIES, LLC BRIAN FRIEDMAN 2805 M STREET, NW WASHINGTON, DC 20007 202-271-4200

### **CONSULTANTS**

MEP:
CHRISTIE DESIGN GROUP
912 THAYER AVE, STE 300,
SILVER SPRING, MD 20910
OFFICE: (301)608-0005

STRUCTURAL:
STRUCTURA INC.
12358 Parklawn Drive, Suite #140
North Bethesda, MD, 20852
(301) 987-9234
Caitlin Mueller, PE
cmueller@structura-inc.com
240.477.1882

SUBMISSIONS								
Date Description								
02.09.2021	BZA APPLICATION							

REVISIO

REVISIONS



Tel 202 452 1644 Fax 202 452 1647 www.bbgm.com

This document and the ideas and designs incorporated within it are instruments of Professional Service. They are and remain the property of


instruments of Professional Service. They are and remain the property of BBGM/Architects & Interiors, Inc. (BBGM) and are not to be used or reproduced in whole or in part for another project without the express written consent of BBGM. Unauthorized additions to or alterations of this document, or to related construction, are prohibited. These drawings are protected by copyright. © 2014 BBGM/Architects & Interiors, Inc.

PROJECT

ALTERATIONS AND REPAIRS AT 2805 M ST, NW

2805 M STREET, NW WASHINGTON, DC 2007

EXTERIOR ELEVATIONS AND SECTIONS




PROJECT No.: 1123.00


DWG No:

A301

ERECT



## **EXTERIOR DETAILS - EGRESS STAIR**



NOTE: PLEASE REFER TO STRUCTURAL DRAWINGS FOR DETAILS AND MEASUREMENTS

2 EXTERIOR EGRESS STAIR SECTION
A302 1/2" = 1'-0"

## 2805 BOND ST. EQUITIES, LLC BRIAN FRIEDMAN 2805 M STREET, NW

**WASHINGTON, DC 20007** 

## **CONSULTANTS**

202-271-4200

CHRISTIE DESIGN GROUP
912 THAYER AVE, STE 300,
SILVER SPRING, MD 20910
OFFICE: (301)608-0005

STRUCTURAL:
STRUCTURA INC.
12358 Parklawn Drive, Suite #140
North Bethesda, MD, 20852
(301) 987-9234
Caitlin Mueller, PE
cmueller@structura-inc.com
240.477.1882

SUBMISSIONS

Date Description

02.09.2021 BZA APPLICATION

REVISION

. Date Descript



Tel 202 452 1644 Fax 202 452 1647 www.bbgm.com


Inis document and the ideas and designs incorporated within it are instruments of Professional Service. They are and remain the property of BBGM/Architects & Interiors, Inc. (BBGM) and are not to be used or reproduced in whole or in part for another project without the express written consent of BBGM. Unauthorized additions to or alterations of this document, or to related construction, are prohibited. These drawings are protected by copyright. © 2014 BBGM/Architects & Interiors, Inc.

PROJECT

ALTERATIONS AND REPAIRS AT 2805 M ST, NW

2805 M STREET, NW WASHINGTON, DC 2007

EXTERIOR ELEVATIONS AND SECTIONS



DWG No:

PARTITION TYPES

✓ NO RATING 2A 1-5/8" STUDS, 1 LAYER OF GYP. BD. EACH SIDE, STEEL STUD OR GYP. BD.

WALL WIDTH

#### DOOR SCHEDULE GENERAL NOTES - DOOR & HDWR

DOOR NUMBER	LOCATION	DOOR SIZE	CONST. TYPE	FINISH TYPE	FRAME	HDWR GROUP
ND-2	2ND FLOOR	2'-8" X 7'-0"	HM	PT	НМ	2
ND-3	2ND FLOOR	2'-8" X 7'-0"	HM	PT	НМ	1

## HARDWARE SCHEDULE


HARDWARE SET	HINGES	CLOSER	LEVER	NOTES
1	Harney Hardware Hinge, Standard Weight, Ball Bearing, 4 1/2" X 4 1/2" HHFBB17910B	Harney Hardware Universal, UL 10C, ANSI Grade 1, Spring 1-4 DC8900DU	Harney Hardware Lock Lever, Entry, Reversible, SAT Style Handle, Schlage "SC 4", UL 10C, ANSI Grade 2 86525	
2	Harney Hardware Hinge, Standard Weight, Ball Bearing, 4 1/2" X 4 1/2" HHFBB17910B	Harney Hardware Universal, UL 10C, ANSI Grade 1, Spring 1-4 DC8900DU	Harney Hardware Lock Lever, Privacy, Reversible, SAT Style Handle, UL 10C, ANSI Grade 2 86528	1HOUR RATE

## WINDOW SCHEDULE


WINDOW NUMBER	LOCATION	WINDOW SIZE	MATERIAL	FINISH TYPE	GLASS TYPE	WINDOW TYPE
W2-1	2ND FLOOR	3'-1" X 5'-2"	WD	PT	SINGLE GLAZED DBL HUNG	DOUBLE HUNG
W2-2	2ND FLOOR	2'-10" X 5'-2"	WD	PT	SINGLE GLAZED DBL HUNG	DOUBLE HUNG
W2-3	2ND FLOOR	2'-9" X 5'-2"	WD	PT	SINGLE GLAZED DBL HUNG	DOUBLE HUNG
W3-1	LOFT FLOOR	2'-7" X 5'-2"	WD	PT	SINGLE GLAZED DBL HUNG	DOUBLE HUNG

NOTE: GC TO FIELD VERIFY THE NEW WINDOW OPENINGS BEFORE PURCHASING ANY MATERIALS.


## DOOR TYPE



## DOOR FRAME



## FRAME DETAIL



1. DOORS THAT ARE NOT LABELED ARE EXISTING TO REMAIN.

FIELD VERIFY ALL OPENINGS, DIMENSIONS AND CONDITIONS AFFECTING WORK PRIOR TO ORDERING AND/OR INSTALLING 2. ALL WINDOWS SHALL BE CAULKED (ALL EDGES) W/ SILICONE SEALANT TO MATCH WINDOW COLOR.

3. UNLATCHING FORCE SHALL NOT EXCEED 15 LBS. IN THE DIRECTION OF TRAVEL. 4. THRESHOLDS SHALL NOT EXCEED 1/2" IN HGT. AND SHALL HAVE BEVELED SIDES THAT SLOPE 1:2 MAXIMUM. 5. ALL EXIT DOORS SHALL BE OPERABLE FROM THE INSIDE WITHOUT USE OF A KEY OR SPECIAL KNOWLEDGE OR EFFORT. 6. ALL DOORS TO BE SELF CLOSING U.N.O.

> 2805 BOND ST. EQUITIES, LLC BRIAN FRIEDMAN 2805 M STREET, NW **WASHINGTON, DC 20007** 202-271-4200

### **CONSULTANTS**

**CHRISTIE DESIGN GROUP** 912 THAYER AVE, STE 300, SILVER SPRING, MD 20910 OFFICE: (301)608-0005 STRUCTURAL: STRUCTURA INC. 12358 Parklawn Drive, Suite #140 North Bethesda, MD, 20852 (301) 987-9234 Caitlin Mueller, PE cmueller@structura-inc.com 240.477.1882

**SUBMISSIONS** Date Description

02.09.2021 BZA APPLICATION

**REVISIONS** 



This document and the ideas and designs incorporated within it are instruments of Professional Service. They are and remain the property of BBGM/Architects & Interiors, Inc. (BBGM) and are not to be used or reproduced in whole or in part for another project without the express written consent of BBGM. Unauthorized additions to or alterations of this document, or to related construction, are prohibited. These drawings are protected by copyright. © 2014 BBGM/Architects & Interiors, Inc.

PROJECT

ALTERATIONS AND REPAIRS AT 2805 M ST, NW

2805 M STREET, NW WASHINGTON, DC 2007

WALL PARTITION SCHEDULE, HARDWARE SCHEDULE AND DETAIL

