


GENERAL NOTES:

1. PROPERTY LINES ARE SHOWN USING GIS INFORMATION AND MOVED TO APPROXIMATE LOCATION. THIS DOES NOT CONSTITUTE A BOUNDARY SURVEY. NO BOUNDARY SURVEY WAS PERFORMED BY ICIVIL.
2. THE WATER LINE WAS NOT MARKED OUT BY 811 AND IS SHOWN USING AVAILABLE RECORDS AS QUALITY LEVEL D INFORMATION. THE LOCATION CANNOT BE RELIED UPON AND TEST PITTING SHOULD BE PERFORMED IN THE AREA AFTER A QLB SURVEY HAS BEEN COMPLETED.
3. THE SEWER FIELD CONNECTION WAS NOT MARKED OUT BY 811 AND IS SHOWN USING AVAILABLE RECORDS AS QUALITY LEVEL D INFORMATION. THE LOCATION CANNOT BE RELIED UPON AND TEST PITTING SHOULD BE PERFORMED IN THE AREA AFTER A QLB SURVEY HAS BEEN COMPLETED.



R HAS FIELD CONNECTION PER
PER MAP B-3-NW

SEWER ADDED BY TRACING
COUNTERMAP B-3-NW SEWER

SSMH=44.56'
ABANDONED

LEGEND

- WIND INDICATOR
- FIRE HYDRANT
- WATER VALVE
- STORM DRAIN MANHOLE
- SEWER MANHOLE
- WATER MANHOLE
- ELECTRIC MANHOLE
- BELL MANHOLE
- LIGHT POLE
- LAMP
- SIGN

TOPOGRAPHIC SURVEY
471-473 H STREET NW
A&T LOTS 834 & 835
SQUARE 517
WASHINGTON, DISTRICT OF COLUMBIA



iCIVIL, Inc.
PROFESSIONAL ENGINEERS, PROFESSIONAL SURVEYORS
LAND PLANNING & CONSTRUCTION MANAGEMENT
10725 BIRMINGHAM WAY
WOODSTOCK, MARYLAND 21163
TEL: (443) 559-6299
www.iCivillinc.com

2nd of Zoning Adjustment
District of Columbia
CASE NO. 21328
EXHIBIT NO. 2