

2019 OCT 16 PM 3:58

2019 OCT 16 PM 3:58

EXHIBIT – G

PICTURE 1 OF 5

PICTURE SHOWING CONDITION OF THE PROPERTY AT THE TIME OF PURCHASE –
BEFORE STARTING CONSTRUCTION – SMALL SHED ON A VACANT LOT – PICTURE TAKEN
FROM REAR OF THE LOT.




2010 DEC 16 PM 3:59

EXHIBIT – G

PICTURE 2 OF 5

PICTURE SHOWING FRONT OF THE BUILDING – PICTURE TAKEN ON THE DAY OF STOP WORK ORDER 11/18/2010 – SHOWS BUILDING STRUCTURE IS COMPLETE AND ALL THE BRICK WORK & ROOF IS DONE.



2010 DEC 16 PM 3:59

EXHIBIT – G

PICTURE 3 OF 5

PICTURE SHOWING REAR VIEW OF THE BUILDING – PICTURE TAKEN ON THE DAY OF STOP WORK ORDER 11/18/2010 – SHOWS BUILDING STRUCTURE IS COMPLETE AND ALL THE SIDING WORK & ROOF IS DONE.



2010 DEC 16 PM 3:59

EXHIBIT – G

PICTURE 4 OF 5

SPRINKLER

PICTURE SHOWING ELECTRICAL & ~~PLUMBING~~ WORK.

- Electrical Rough-Ins are complete and ready to be closed by Drywalls. Complete network of electrical wires / cables is installed as 3 units. Individual electrical panels are installed and utility company is working to provide power as 3-units.
- Rough-Ins for Fire Sprinkler is complete and ready to be closed by Drywalls. Complete fire sprinkler system installed and water pipes network is installed as 3-units.

PICTURE TAKEN ON THE DAY OF STOP WORK ORDER 11/18/2010.



2010 DEC 16 PM 3:59

2010 DEC 16 PM 3:59

EXHIBIT – G

PICTURE 5 OF 5

PICTURE SHOWING PLUMBING & HVAC WORK.

- Plumbing Rough-Ins are complete and ready to be closed by Drywalls. Complete network of water and gas pipes is installed for baths, kitchens & appliances as 3 units. Bath tubs are installed. Gas and Water utility companies are working to provide utilities as 3-units.

- HVAC Rough-Ins are complete and ready to be closed by Drywalls. All the Duct Work is done as 3 units. 3 Furnaces are installed to serve 3 separate units.

PICTURE TAKEN ON THE DAY OF STOP WORK ORDER 11/18/2010.

