





A black and white photograph showing a building in the process of being demolished. On the left, a large, dark, classical-style column is partially visible. The main building has a two-story structure. The upper story is mostly missing, leaving a skeletal frame of vertical studs and horizontal beams. A line points from an annotation box to the top edge of this upper story. Below the upper story, there is a smaller, single-story section with a gabled roof. Another annotation box points to a section of the wall on this lower level. The background shows bare trees and a light sky.

WEST WALL - NEW CONSTRUCTION
PORCH BEFORE BEING DEMOLISHED
- PHOTO TAKEN 03/05/2013

NOTE ORIGINAL
ROOF LINE

AREA LATER
REMOVED FOR
PLACEMENT OF
HVAC UNIT

LINE SHOWING HEIGHT OF NEW A-FRAME ROOF
APPROXIMATE 2 FEET TALLER
PHOTO TAKEN 11/04/2013

