



Exterior Perspectives - Closed

12/17/2013



Kitchen Perspective View



Living Area Perspective View



Open Apartment Kitchen Perspective View



Closed Apartment Kitchen Perspective View



Roof Terrace Perspective View



Existing Condition



Proposed



Three existing carriage house residences already stand in Walker Court. Building #3 was a one story garage until 1983.



Existing Carriage Houses on Site



Rear: Existing Rear Brick Wall with case-ment windows to be repaired or restored. Failing brick wall to be removed and brick salvaged for reuse.



Front: Existing Brick Doorway opening and wall to remain, for new window, to match existing casement windows.

