

Photographs of the Property





FRONT OF PROPERTY FROM 8TH STREET NW

Photographs of the Property





OPEN COURT AT REAR OF PROPERTY

Photographs of Structural Damage



Photographs of Structural Damage



Photographs of Structural Damage



Photographs of Dilapidated Condition

