

Supporting Document for Application of Diana Kurnit and Jonathan Brumer
5330 42nd Street NW, Washington, D.C. 20015

Photos Taken After Deck Demolition



View of rotten wood over our garage, which was behind the old deck and has since been repaired.



Water damage from old deck caused terrible rot, and has since been repaired.



Water damage from old deck over our shed and basement door (has since been repaired.)



View out of kitchen door down to ground one story below, showing current hazardous condition in absence of deck (which worries us as we have two small children.)