

TAB G


Photographs of the Interior of 1212-1218 4th Street NW



Collapsed Roof



Collapsed Roof




Electrical Outlet




Oil Storage Tank

Photographs of the Interior of 1212-1218 4th Street NW



Exposed Foundation



Collapsed Stairwell