




Board of Zoning Adjustment
District of Columbia
CASE NO.19203
EXHIBIT NO.9

Board of Zoning Adjustment
District of Columbia
CASE NO.19203
EXHIBIT NO.9






SIDE VIEW OF SUBJECT PROPERTY




SOUTH FACADE OF ADJACENT CONDOMINIUM (ON THE LEFT) SHOWING NO DOOR OR WINDOW OPENINGS



SUBJECT PROPERTY IN THE MIDDLE, FLANKED
BY A CONDOMINIUM (ON THE LEFT) AND AN
APARTMENT HOUSE (ON THE RIGHT)





KENDALL STREET (VIEWING NORTH) SHOWING AND
APARTMENT HOUSE (ON THE LEFT) AND A DETACHED SINGLE
FAMILY DWELLING (ON THE RIGHT)

