


Erosive drainage off back slope of "Ft Stanton" apartment site facing park & trail

5-4-99

BZA
CASE No. 16457
EXHIBIT No. 48

Board of Zoning Adjustment
District of Columbia
CASE NO.16457
EXHIBIT NO.48



View of fill site from park
45' rise
Ft Stanton 5-4-99



Fill site overlooking park trail to right Ft Stanton 5-4-99



View of fill site from trail
Ft Stanton Peak 5-4-99



View from top of fill site into park overlooking trail ~45' down
Ft Stanton Park 5-4-99



erosion into porch from apartment site Ft Stanton 5.4.99



gullying on fill site

5.4.99



Wetland "seep" Ft Stanton
Lady ferns

5-4-99

BZA
CASE No. 16457
EXHIBIT No. 48



lady fern, magnolia, spicebush
wetland seep or bog
Ft Stanton 5-4-99



Sweet bay Magnolia
in Wetland "seep"
Ft. Stanton 5-4-99



Wetland seep, Ft Stanton
ferns, jewel weed, spicebush