
...ey for title purposes only - not to be used for determining property lines. Property corner markers not guaranteed by this survey.



BUILDING LOCATION
LOT 819, SQUARE 877
WASHINGTON
DISTRICT OF COLUMBIA

BZA
Case No. 16825
Exhibit No. 4

Lot 819 shown A & T Tracings
Note: Not in Flood Plain per Existing Records

STATE OF MARYLAND
JEFFERSON D. LAWRENCE
No. 5216 REGISTERED
PROFESSIONAL LAND SURVEYOR

RECEIVED
D.C. OFFICE OF ZONING
2015 MAR 02 A 7:10

SURVEYOR'S CERTIFICATE

I HEREBY CERTIFY THAT THE POSITION OF ALL THE EXISTING IMPROVEMENTS ON THE ABOVE DESCRIBED PROPERTY HAS BEEN CAREFULLY ESTABLISHED BY A TRANSIT-TAPE SURVEY.

JEFFERSON D. LAWRENCE
REGISTERED LAND SURVEYOR MARYLAND # 5216

REFERENCES	ANDJON ASSOCIATES
PLAT BK.	7 Brookes Avenue Gaithersburg, Maryland 20877 (301) 840-9010
PLAT NO.	
LIBER	DATE OF SURVEYS:
FOLIO	WALL CHECK:
	LOC. 7-14-87
	BOUNDARY:
	SCALE: 1" = 20'
	DRAWN BY:
	JOB NO. 19706

61763-82883

Board of Zoning Adjustment
District of Columbia
CASE NO.16825
EXHIBIT NO.4