




Deforested Parkland









Post-construction view of Walled Platform Structure
from Tate Property - new house in background -
mesh fence near bottom of photo marks property line



Preconstruction view from Tate Property - Old Economides house in background.



Preconstruction view from Tate Property



Pre-construction view from Tate Property



Preconstruction view from Tate Property


← Appellant's House



View of Appellant's House from above terrace of
Walled Platform Structure.




Part of Surface of Walled Platform Structure - Feb. 2005



Examples of mud oozing from cracks between mesa blocks







Silt fence located on NPS/Wesley Heights Park
Property



View of bulges and undulations in wall.









C

BEFORE THE BOARD OF ZONING ADJUSTMENT
OF THE DISTRICT OF COLUMBIA

Appeal of Patrick J. Carome

of Building Permit
No. B460927

4825 Dexter Terrace, NW
Frank & Dina Economides, Owners

BZA Appeal No. 17285

Hearing Date: March 1, 2005

APPENDIX OF EXHIBITS TO BRIEF OF APPELLANT
PATRICK J. CAROME VOL 2 OF 2

RECEIVED
D.C. OFFICE OF ZONING
2005 FEB 16 AM 10:20

Patrick J. Carome
David Donovan
Katie Reilly
WILMER CUTLER PICKERING
HALE AND DORR LLP
2445 M STREET, N.W.
WASHINGTON, DC 20037
Tel: 202-663-6000
Fax: 202-663-6363

Counsel for Appellant

February 15, 2005

BZA
Case No. 17285
Exhibit No. 21-C

**BEFORE THE BOARD OF ZONING ADJUSTMENT
OF THE DISTRICT OF COLUMBIA**

Appeal of Patrick J. Carome, BZA Appeal No. 17285

Exhibits in Support of Appeal

Table of Contents

Affidavits

Exhibit 1	Affidavit of James W. Heltman
Exhibit 2	Affidavit of Harry Gates

Provisions of the D.C. Code

Exhibit 3	Wesley Heights Overlay District, 11 DCMR §§ 1541 - 1543
Exhibit 4	Rear & Side Yard Requirements, 11 DCMR §§ 404 - 405
Exhibit 5	Structures in Required Open Spaces, 11 DCMR § 2503
Exhibit 6	Definition of "Structure," 11 DCMR § 199
Exhibit 7	Meaning of Terms not Defined by Code, 11 DCRM § 199.2(g)
Exhibit 8	Advisory Neighborhood Commission, 11 DCMR § 3115
Exhibit 9	Advisory Neighborhood Commissions, D.C. Code § 1-309.10
Exhibit 10	Advisory Neighborhood Commissions, D.C. Code Art. X § 1001
Exhibit 11	Required Permits, 12 DCMR § 105.1
Exhibit 12	Application for and Certification of Permits, 12 DCMR § 105.3
Exhibit 13	Required Inspections, 12 DCMR § 109.3
Exhibit 14	Third-Party Inspection Agencies, 12 DCMR § 109.4
Exhibit 15	Fill Materials, 12 DCMR § 3303.4.3
Exhibit 16	Land Disturbing Activities, 21 DCMR § 502
Exhibit 17	Definition of Land Disturbing Activities, 21 DCMR § 21 DCMR § 599
Exhibit 18	Erosion Control Principles: Design, 21 DCMR § 539

Court Decisions

Exhibit 19	<i>Ranson v. City of Charleston</i> , 496 S.E.2d 191 (W.Va. 1997)
Exhibit 20	<i>Adler v. Craft</i> , A-1-03T5 (N.J. Sup. Ct. App. Div. Sept. 22, 2004)

***Definitions from Webster's Third New International Dictionary of the English Language
Unabridged Version***

Exhibit 21	"construct," "fence," "platform," "retaining wall," "terrace," and " wall"
------------------	--

Maps and Plans

Exhibit 22	Surveyor's Maps of Affected Lots
Exhibit 23	CAS Drawing of Plans for Walled-Platform Structure
Exhibit 24	Ryan & Associates' Final Designs for Walled-Platform Structure
Exhibit 25	David Jones Architects Plans for Economides' New Home/CAS Site Plan
Exhibit 26	D.C. Tax Assessment of 4825 Dexter Terrace
Exhibit 27	Letter from Specialized Engineering
Exhibit 28	Wall Tests of 4825 Dexter Terrace, 1950 and 2003

Photographs

Exhibit 29	Deforested Parkland
Exhibit 30	Post-Construction View of Walled-Platform Structure from Tate Property
Exhibit 31	Pre-Construction View of Walled-Platform Structure from Tate Property
Exhibit 32	View of Walled-Platform Structure from Appellant's Home
Exhibit 33	Walled-Platform Structure Surface
Exhibit 34	Mud Oozing from Walled-Platform Structure
Exhibit 35	Silt Fence on NPS Property
Exhibit 36	Bulges and Waves in Walled-Platform Structure
Exhibit 37	Cracked Mesa Blocks (Individuals)
Exhibit 38	Cracked Mesa Blocks (In Groups)
Exhibit 39	Diagrams of Locations of Cracked Mesa Blocks
Exhibit 40	Rocks and Debris in Fill Material
Exhibit 41	Separating Wall Joints
Exhibit 42	New Economides Home
Exhibit 43	Silt Damage in Wesley Heights Park
Exhibit 44	Concentrated Water Discharge From Walled-Platform Structure
Exhibit 45	Walled-Platform Structure Encroaching on U.S. Parkland
Exhibit 46	Activity During Stop Work Orders

Proceedings Against Economides

Exhibit 47	Criminal Complaint Filed in D.C. Superior Court
Exhibit 48	Press Release from Office of the Attorney General for the District of Columbia
Exhibit 49	Email from Assistant U.S. Attorney
Exhibit 50	Department of Health Decision

Applications and Permits

Exhibit 51	Application for Permit to Build "New Retaining Wall"
Exhibit 52	Permit No. B460927 for construction of "New Retaining Wall"
Exhibit 53	Forged Permit No. 445054 for "Emergency Razing"
Exhibit 54	Permit No. 44054 and Application for Razing at 2970 Chain Bridge Road
Exhibit 55	Electrical Permits Obtained Pursuant to Forged Permit No. 445054
Exhibit 56	Application for Permit to Fill Rear Yard and Regrade Rear Yard

Exhibit 57 Permit No. 422839 to Fill Rear Yard and Regrade Rear Yard
Exhibit 58 Application for Permit for Renovation and Addition to Single Family Dwelling
Exhibit 59 Permit No. B425076 for Renovation and Addition to Single Family Dwelling
Exhibit 60 Application for Permit for New House Construction
Exhibit 61 Permit No. B452810 for New House Construction
Exhibit 62 Permit No. B468560 to "Technically Correct" Permit No. B452180
Exhibit 63 Correct Form for Application for Permit to Build Retaining Wall

Correspondence

Exhibit 64 Letter to Caromes from Denzil Noble Dated December 9, 2004
Exhibit 65 First and Only Weekly Update from DCRA
Exhibit 66 Email from Elizabeth Carter to Elsie Carome Dated November 11, 2004
Exhibit 67 FOIA Request and Follow-Up Letter
Exhibit 68 Caromes' Request for Explanation

ANC Submissions

Exhibit 69 Carome Submission
Exhibit 70 Submission by Richard Aguglia on Behalf of Economides



