



1. VIEW OF SUBJECT PROPERTY FROM D STREET SE



2. VIEW OF WEST SIDE OF SUBJECT PROPERTY

The narrow 'gap' between the subject property and the house on the lot immediately to the west affords a glimpse of the west side of the structure..



3. REAR VIEW OF 328 D STREET SE

The adjacent brick structure encroaches on the subject property by approximately 1.4'.



4. VIEW OF EXISTING REAR ADDITION ON ADJACENT PROPERTY

The stucco portion of this structure (326 D St. SE) was built in 2008. The same type of relief the applicant seeks was required to build this addition.

www.chevychasearchitect.com