



FRONT ELEVATION



STREET VIEW WITH TOWNHOUSES



STREET VIEW WITH APARTMENTS



524 JEFFERSON ST. EXISTING CONDITIONS

Board of Zoning Adjustment
District of Columbia
CASE NO. 19761
Issue Date:
4/30/2018
EXHIBIT NO. 49




VIEW ACROSS THE STREET



BACK OF THE TOWNHOUSE



BACK OF THE TOWNHOUSE FROM THE ALLEY



TANDEM PARKING AT 610 JEFFERSON



524 JEFFERSON ST. EXISTING CONDITIONS

Issue Date:
4.30.2018



VIEW BETWEEN 608 AND 524 JEFFERSON IN THE BACK. PHOTO TAKEN IN THE MORNING ON JUNE SHOWING THE SHADOW CAST FROM 524 TO 608



BACK OF THE TOWNHOUSE AND SHADOW CAST BY 608 JEFFERSON TO 524 JEFFERSON - PHOTO TAKEN IN THE AFTERNOON IN MAY



VIEW BETWEEN 608 AND 610 JEFFERSON IN THE BACK. PHOTO TAKEN IN THE MORNING ON JUNE SHOWING THE SHADOW CAST FROM 608 TO 610



524 JEFFERSON ST. EXISTING CONDITIONS

Issue Date:
4.30.2018