



WALL CHECK

Register

During the review process DOB reviewers might request additional information (in text or document format) from you within the application. Find pending requests listed here.

B2508907

4401 Garrison St, N.W.
Lot 80 or 1501

Zoning review 1

Status

Failed

REVIEWER - EDWIN ANDINO

Review requested on May 14 2026, 4:01 pm

Note

Applicant received relief from the BZA for a 15.2' rear setback, and the built structure provides a 13.46' rear setback which increases,

Board of Zoning Adjustment
District of Columbia
CASE NO. 21374A
EXHIBIT NO. 14A

Wall check was
REJECTED by Zoning

DISTRICT OF COLUMBIA GOVERNMENT
Office of the Surveyor

Wall Report for.....SQUARE 1581.....LOT 80.....

Scale: 1 inch = 20 feet Recorded in Book 97 Page 54

S.O. SEAL

S.O. Receipt No.226542.....

Received by
Surveyor , D.C.

Date:

REGISTERED LAND SURVEYOR'S CERTIFICATION

I certify that the wall locations shown hereon have been determined by me, or under my direction, in accordance with Chapter 28 of Title 10 DCMR, and that I have not engaged in the construction layout on this site.



Glen Kump

Signature

4/28/2026


DATE _____

RLS SEAL

 $\frac{W}{Z}$

STREET,

44TH



GARRISON

STREET,

N.W.

METAL FORMS LOCATED