



Image A: Existing North Elevation with adjacent neighboring properties



Image B: Existing North Elevation with public alley



Image C: Existing West elevation from Sedgwick ST NW



Image D: Existing West elevation from public alley



Image E: Existing fence from public alley

Rodriguez Residence

4726 Sedgwick St NW, DC, 20016

www.kg-rw.com

Special Exception

04/24/23

3454 Ellicott Center Drive, Suite 107, Ellicott City, MD 21043

410.680.8900

hello@kg-rw.com

Board of Zoning Adjustment
District of Columbia
CASE NO. 20142
EXHIBIT NO. 3
KGRW & Associates, LLC



Image F: Existing East Elevation



Image G: Existing East elevation



Image H: View of neighboring property to east



Image I: Existing South elevation with adjacent building to the right of the photo

Rodriguez Residence

4726 Sedgwick St NW, DC, 20016

www.kg-rw.com

Special Exception

04/24/23

3454 Ellicott Center Drive, Suite 107, Ellicott City, MD 21043

410.680.8900

hello@kg-rw.com


KGRW & Associates, LLC