

Photo I: Front facade of 4725 Yuma Street



Photo A: rear yard of 4725 showing slope of grade and abutting east and west neighbors



Photo B: Existing accessory garage in relation to existing house and west abutting neighbor



Photo C: Existing accessory garage in relation to rear yard grade and adjacent garage across alley



Photo D: existing accessory garage from rear of existing house looking towards alley




Photo E: existing accessory garage from alley looking west



Photo F: west abutting neighbor with single story addition adjacent to shared property line



Photo G: Existing addition at 4725 with addition of west abutting neighbor beyond



Photo H: rear yard of 4725 looking towards east abutting neighbor at higher grade

