



WALL CHECK

Register

During the review process DOB reviewers might request additional information (in text or document format) from you within the application. Find pending requests listed here.

B2508907

*4401 Garrison St, N.W.
Lot 80 or 1501*

Zoning review 1

Status

Failed

REVIEWER - EDWIN ANDINO

Review requested on May 14 2026, 4:01 pm

Note

Applicant received relief from the BZA for a 15.2' rear setback, and the built structure provides a 13.46' rear setback which increases,

Board of Zoning Adjustment
District of Columbia
CASE NO. 21374A
EXHIBIT NO. 3

*Wall check was
REJECTED by Zoning*

DISTRICT OF COLUMBIA GOVERNMENT
Office of the Surveyor

Wall Report for.....SQUARE 1581.....LOT 80.....

Scale: 1 inch =20..... feet..... Recorded in Book97..... Page54.....

S.O. SEAL


S.O. Receipt No.226542.....

Received by
Surveyor, D.C.



Date:

REGISTERED LAND SURVEYOR'S CERTIFICATION

I certify that the wall locations shown hereon have been determined by me, or under my direction, in accordance with Chapter 28 of Title 10 DCMR, and that I have not engaged in the construction layout on this site.


Signature
4/28/2026
DATE

RLS SEAL



GARRISON STREET, N.W.

METAL FORMS LOCATED