




key

- 1 subject property: 114 3rd St
- 1 existing accessory garage
- 2 adjacent property: 118 3rd St
- 3 adjacent property: 301 A St (Saint Mark's Church)
- 4 adjacent property: 120 2nd St (Library of Congress John Adams Building)

site context

key



- 1 subject property: 114 3rd St
- 2 adjacent property: 118 3rd St
- 3 adjacent property: 301 A St (Saint Mark's Church)
- 4 adjacent property: 120 2nd St (Library of Congress John Adams Building)



existing conditions | west facade



- 1 view of front facade (3rd St SE)
- 2 view of front door
- 3 view of front gate
- 4 view of sidewalk / 3rd street




keyplan (nts)



existing conditions | courtyard



- 1 view of rear facade
- 2 view of garage
- 3 view of garage from deck
- 4 view of garage entry



keyplan (nts)

existing conditions | context



- 1 street view of property from library court
- 2 street view of 301 A St & library court se
- 3 street view of library of congress john adams building from 3rd st se
- 4 street view of garage entry

