

# Existing Building

---



Entry Door





# Existing Building

---



# Existing Conditions

---



Corridor



Common restroom



Overview of kitchen



Overview of club house

# Existing Conditions



Common Laundry Room



Boilers are located at basement.



Overview of roof

TPO roofing



Gas Water Heater

# Existing Conditions



Common restroom



Common Restroom



Main kitchen located at first floor

# Existing Conditions Sample Unit



Overview of Unit 205



Overview of Unit 326



# Existing Conditions

---



Overview of Unit 324



Overview of Unit 306



Overview of Unit 312